



CemAir (Proprietary) Limited

*Hangar 6, Eastern Precinct,
OR Tambo International Airport
Kempton Park*

03 February 2018

CemAir (IATA code 5Z) regrets to advise that due to a documentation issue identified by the SACAA in the annual audit of the CemAir AMO (aircraft maintenance organization) CemAir's domestic flights have been suspended.

CemAir is working with the SACAA to resolve the issue as expeditiously as possible and will be meeting with them over the weekend. As information becomes available we will issue further press releases.

At the time of writing it is unclear how long this situation will persist, however we will make further announcements in due course regarding resumption of service.

In the interim the airline is making alternate arrangements for passengers where possible. We are working closely with other carriers to accommodate our passengers with minimum inconvenience. Alternately all passengers can apply for a full refund.

Please contact our call centre on 0861 236 247 for further information. Understandably we are experiencing high call volumes and appreciate your patience during this time.

CemAir remains committed to serving our passengers and regrets the inconvenience caused by the interruption of service.

Plating Carrier – 5Z (CemAir PTY Ltd)

IATA Accounting Code: 225

Linked BSP: ZA, UK & Germany